Babytherm 8004/8010
Technical Service Bulletin # 5

Re:	**Replacing Controller PCB, new Software Version 1.01**
Date:	April 30, 2001
Reference Doc:	Service Bulletin from Dräger Medizintechnik GmbH: 6132.300 Babytherm 8004/8010 # 5, February 16, 2001
Reason:	A new EEPROM on the Controller PCB P/N 8290674 requires the new software version 1.01. If a new Controller PCB is used with the previous software version error code 15 will be generated.
Solution:	When replacing the PCB Controller P/N 8290674, software version 1.01 must be installed.
Devices affected:	All units Babytherm 8004/8010 with installed software version 1.00.
When:	With next replacement of Controller PCB P/N 8290674.
Reporting:	N/A
Additional Info:	N/A
Cost:	Covered by Customer, post warranty.
Ordering Info:	EPROM SW1.01 Babytherm 8004/8010 P/N 2M 30 440
Distribution:	Dräger Service Personnel and Authorized Service Organizations.

If you have any questions, please contact Technical Support by phone at 1-800-543-5047 or by fax at 1-215-721-5789.

Dräger Medical, Inc.
Technical Product Manager